

Work Order ID 58375

May 5, 2010 8:04:49 AM



Page 1

Item ID: D2690-6

Accept



Setup Start



Revision ID:

Item Name: Lanyard Assembly

Stop



Start Date: 05/05/2010 Start Qty: 50.00



Cust Item ID:

Required Date: 10/05/2010 Req'd Qty: 50.00



Customer:

Reference:

Approvals:

Process Plan:

PH

Date:

10-5-05

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D2690

Rev B2

100

0.00



Small Fab

Small Fab

Memo

0.00

Small Fab

Assemble as per Dwg D2690 Identify as D2690-6

ES 10/05/10 (50)

110

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

5/10/05/10

center (50)

120

Identify as per dwg & Stock Location: *021*

0.00



Packaging

Memo

0.00

Packaging

Rec 5/11 (50)

W/O:			WORK ORDER CHANGES					
DATE	STEP		PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:			WORK ORDER NON-CONFORMANCE (NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 58375

May 5, 2010 8:04:49 AM



Page 2

Item ID: D2690-6

Accept



Setup Start



Revision ID:

Item Name: Lanyard Assembly

Stop



Start Date: 05/05/2010 Start Qty: 50.00



Cust Item ID:

Required Date: 10/05/2010 Req'd Qty: 50.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursDraw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/05/12 *[Signature]*
mf
10-5-11

W/O:			WORK ORDER CHANGES					
DATE	STEP		PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:			WORK ORDER NON-CONFORMANCE (NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

May 5, 2010 8:04:54 AM

Page 1

Work Order ID: 58375

Parent Item: D2690-6

Parent Item Name: Lanyard Assembly


Comments: IPP: C□C□03.04.04□Reformat; Incorporated D2690-X□KJ/RF□

Start Date: 05/05/2010

Required Date: 10/05/2010

Start Qty: 50.00

Required Qty: 50.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
CBL-460  Loop Sleeve		Purchased	No			100	Each	89.0000	2			

Location

ST285

113002

Loc Qty

89

89

Loc Code

EBro/05/10
M114622 (39x)

CBL-1240



Cable

Purchased

No

110

Each

471.7688

1

Location

ST275

113565

Loc Qty

471.7688

471.7688

Loc Code

EBro/05/10
61
36.5

W/O:			WORK ORDER CHANGES					
DATE	STEP		PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:			WORK ORDER NON-CONFORMANCE (NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>ME</i>	DRAWN BY <i>KE</i>	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA	
CHECKED <i>ME</i>	APPROVED <i>BW</i>	DRAWING NO. D2690	REV. B SHEET 1 OF 1
DATE 97.10.02		TITLE LANYARD ASSEMBLY	SCALE NTS
A	97.07.03	NEW ISSUE	
B	97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH	
B1	CP 01.08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE	
B2	CP 04.06.24	ADDED TOLERANCE	

RELEASED
971003 KE
TSR A374



D2690-X

X = LENGTH IN INCHES

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 58325

BS10-5-05

NOTE: CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTH.
FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH
SLEEVE AT END OF LOOSE END OF CABLE WITH
CBL-705 CRIMPING TOOL.

*ADDITIONAL LENGTH MAY BE NECESSARY IN
SOME APPLICATIONS. CUT AS REQUIRED.

NOTE: IN SOME CASES, END HAS TO BE CRIMPED AFTER
ASSEMBLY WITH ATTACHING PARTS.

DEO's

W/O:			WORK ORDER CHANGES					
DATE	STEP		PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:			WORK ORDER NON-CONFORMANCE (NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries